

Stability Certificate

Whom so Ever it May Concern, this is to Certify that the Undersigned Visited for the Construction The Aditya Birla Public School @ Village Keshrol Village, Bharuch-Dahej Highway, Bharuch. The Structure is Sound, Safe & in Good Stable Condition. On the Basis of Test Results of NDT Tests Conducted at this Site on November 20, 2016. & Our Experience in this Regards. The Structure is Capable to withstand Till Next 25 Years.

Declaration

I Hereby Declare that

1. I Have Personally Inspected the Property On November 20, 2016.
2. I Have no Direct or Indirect Interest in the Property Inspected for Stability Certification.
3. The Information Furnished in Above is True & Correct to the Best of my Knowledge & Belief.

Date : November 25, 2016.



Place : Bharuch.

Signature of Registered Engineer

DHARMESH INTWALA
B.E.(Civil), M.I.E., F.I.V.
Chartered Engineer
(Reg. No. M-146251-17)
GPCPSIRDA Reg. No. GPCPSIRDA/Engineer/07
Opp. Shree K. J. Polytechnic College,
Old N. H. No. 8, Bholav, Bharuch-392002
Mo.-98241 02436